


Date: 10/9/06

To: Distribution

From: P. Bergh  10/10/06

Subject: Safety Walk

On October 9, 2006 a Safety Walk of the F-Super period was performed. The task performed was decontamination and survey of the posted CONTAMINATION AREA at F-9 through F-12.

Safety Walk Attendees:

M. Robles (C-A Health Physics)
D. Aichroth (C-A Health Physics)
J. Scott (C-A ESH&Q)
E. Lacina (C-A ESH&Q)
P. Bergh (C-A Health Physics)

Positive Observations:

- Decontamination and surveys performed as per BNL procedures and BNL Radiological Control Manual.
- Work performed while incorporating good ALARA practices.
- Required safety and radiological PPE worn during work.
- Pre-job walk through with CAS personnel performed to identify any specific hazards.

Negative Observations:

Cable with cracked and deteriorated insulation identified. Work Control coordinator notified.